

Existing Conditions: Central Corridor crossing of Ruby Road looking westbound.



Visual Simulation: Depicting dulled galvanized lattice towers.

Visual Simulation 12: Central Corridor Crossing of Ruby Road.

Wide-open view of the Central Corridor from a Concern Level 1 travelway.

Direction: Southwest

Distance to Nearest Pole: 0.2 mi



July 2003 4-46